

Table 5-1. Outfall Inventory and Priority Ranking Matrix
Auburn, Massachusetts
Revision Date: September 28, 2019

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/ Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
I-22	Auburn Pond	0	0	0	0	2	3	0	0	0	None	5	Low Priority
A-04	Chapin Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
B-13	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-31	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-32	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-33	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-34	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-35	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-36	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-39	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-40	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-41	Dark Brook from Dark Brook Reservoir to Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-01	Dark Brook Reservoir	0	0	0	0	1	0	0	3	0	None	4	Low Priority
G-02	Dark Brook Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-03	Dark Brook Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-04	Dark Brook Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-06	Dark Brook Reservoir	0	0	0	0	2	3	0	0	0	None	5	Low Priority
G-23	Dark Brook Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-14	Dark Brook Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-50	Dark Brook Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-01	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-02	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-03	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-04	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-05	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-06	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-07	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-08	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
C-09	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-10	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-11	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-12	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	1	None	6	High Priority
C-13	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-14	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-15	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-16	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-17	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-50	Dark Brook/Ramshorn Brook	0	0	0	0	3	3	0	0	0	None	6	High Priority
C-51	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-52	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-53	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-56	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	1	None	6	High Priority
C-57	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-58	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-62	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-63	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-64	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-65	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-66	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-67	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-68	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-69	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-70	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-71	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
C-75	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-76	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-77	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	1	None	6	High Priority
H-01	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-02	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
H-03	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-04	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-05	Dark Brook/Ramshorn Brook	0	3	0	0	1	3	0	0	0	None	7	High Priority
H-06	Dark Brook/Ramshorn Brook	0	3	0	0	1	3	0	0	0	None	7	High Priority
H-07	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	1	None	5	Low Priority
H-08	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-09	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	1	None	5	Low Priority
H-10	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-11	Dark Brook/Ramshorn Brook	0	3	0	0	2	3	0	0	0	None	8	High Priority
H-12	Dark Brook/Ramshorn Brook	0	3	0	0	2	3	0	0	0	None	8	High Priority
H-15	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-16	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-17	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-18	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-19	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-20	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-26	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-35	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-36	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-37	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-38	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-39	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-40	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-41	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-42	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-43	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-44	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-45	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-46	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-47	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-48	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
H-49	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-51	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-52	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-53	Dark Brook/Ramshorn Brook	0	3	0	0	2	3	0	0	0	None	8	High Priority
H-54	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-55	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-56	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-57	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-58	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	1	None	5	Low Priority
H-61	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-62	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-64	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-65	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-26	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-07	Dark Brook/Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
M-08	Dark Brook/Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-06	Diversion Channel	0	0	0	0	2	3	0	0	0	None	5	Low Priority
E-07	Diversion Channel	0	0	0	0	2	3	0	0	0	None	5	Low Priority
E-08	Diversion Channel	0	0	0	0	2	3	0	0	0	None	5	Low Priority
E-09	Diversion Channel	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-12	Diversion Channel	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-13	Diversion Channel	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-27	Diversion Channel	0	0	0	0	1	3	0	0	0	None	4	Low Priority
L-01	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
L-02	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
L-03	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
L-04	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
L-05	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
L-06	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
L-07	Eddy Pond	0	0	0	3	1	0	0	3	0	None	7	High Priority
C-35	Kettle Brook	0	0	0	2	2	3	0	0	0	None	7	High Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
C-40	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-41	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-42	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-43	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-44	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-45	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-46	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-47	Kettle Brook	0	0	0	2	2	3	0	0	0	None	7	High Priority
C-48	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-49	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-54	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-55	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-59	Kettle Brook	0	0	0	2	2	3	0	0	0	None	7	High Priority
C-61	Kettle Brook	0	0	0	2	2	3	0	0	0	None	7	High Priority
C-73	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-74	Kettle Brook	0	0	0	2	1	3	0	0	0	None	6	High Priority
C-21	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
C-22	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
C-23	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
D-01	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
D-02	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
D-03	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
D-05	Leesville Pond	0	0	0	3	1	3	0	0	1	None	8	High Priority
D-06	Leesville Pond	0	0	0	3	1	3	0	0	1	None	8	High Priority
D-4	Leesville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
M-05	Pondville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
M-06	Pondville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
M-10	Pondville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
M-11	Pondville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
M-12	Pondville Pond	0	0	0	3	1	3	0	0	0	None	7	High Priority
M-13	Pondville Pond	0	0	0	3	2	3	0	0	1	None	9	High Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
I-01	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-02	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-03	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-04	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-05	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-06	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-07	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-08	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-09	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-10	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-11	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-12	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-13	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-14	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-15	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-16	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-17	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
I-18	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-19	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-20	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-21	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-23	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-24	Ramshorn Brook	0	0	0	0	1	3	0	0	1	None	5	Low Priority
I-25	Ramshorn Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
I-27	Ramshorn Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
M-14	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
M-15	Stone Brook	0	0	0	0	1	0	0	3	1	None	5	Low Priority
M-17	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
M-18	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
M-19	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
M-21	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
M-22	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
M-23	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
M-24	Stone Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
B-02	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-03	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-04	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-14	Stoneville Pond	0	0	0	0	2	3	0	0	0	None	5	Low Priority
B-15	Stoneville Pond	0	0	0	0	2	3	0	0	0	None	5	Low Priority
B-16	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-17	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-18	Stoneville Pond	0	0	0	0	2	3	0	0	0	None	5	Low Priority
B-19	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-20	Stoneville Pond	0	0	0	0	2	3	0	0	0	None	5	Low Priority
B-21	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-22	Stoneville Pond	0	0	0	0	2	3	0	0	0	None	5	Low Priority
B-23	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-24	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-25	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-26	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-27	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-28	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-37	Stoneville Pond	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-38	Stoneville Pond	0	0	0	0	1	0	0	3	0	None	4	Low Priority
A-01	Stoneville Reservoir	0	0	0	0	1	0	0	3	0	None	4	Low Priority
A-02	Stoneville Reservoir	0	0	0	0	1	0	0	3	0	None	4	Low Priority
A-03	Stoneville Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
A-09	Stoneville Reservoir	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-08	Tinker Hill Pond	0	0	0	0	1	0	0	3	0	None	4	Low Priority
G-09	Tinker Hill Pond	0	0	0	0	1	0	0	3	0	None	4	Low Priority
J-01	Tributary to the French River in Oxford	0	0	0	0	1	3	0	0	0	None	4	Low Priority
J-02	Tributary to the French River in Oxford	0	0	0	0	1	3	0	0	0	None	4	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
J-03	Tributary to the French River in Oxford	0	0	0	0	1	3	0	0	1	None	5	Low Priority
J-04	Tributary to the French River in Oxford	0	0	0	0	2	3	0	0	0	None	5	Low Priority
J-05	Tributary to the French River in Oxford	0	0	0	0	2	3	0	0	0	None	5	Low Priority
J-06	Tributary to the French River in Oxford	0	0	0	0	2	3	0	0	0	None	5	Low Priority
G-05	Unnamed Trib to Dark Brook Reservoir Crossing Southbridge St @ Warren Rd	0	0	0	2	1	3	0	0	0	None	6	High Priority
G-07	Unnamed Trib to Dark Brook Reservoir Crossing Southbridge St @ Warren Rd	0	0	0	2	1	3	0	0	0	None	6	High Priority
G-22	Unnamed Trib to Dark Brook Reservoir Crossing Southbridge St @ Warren Rd	0	0	0	2	1	3	0	0	0	None	6	High Priority
E-05	Unnamed Trib to Diversion Channel Crossing Pinrock Rd	0	0	0	0	2	3	0	0	0	None	5	Low Priority
E-20	Unnamed Trib to Diversion Channel Crossing Pinrock Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-21	Unnamed Trib to Diversion Channel Crossing Pinrock Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-22	Unnamed Trib to Diversion Channel Crossing Pinrock Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-10	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-11	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-14	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-15	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-16	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-17	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-18	Unnamed Trib to Diversion Channel Crossing Southold Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-01	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	1	None	5	Low Priority
E-02	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-03	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-04	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-19	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-23	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	1	None	5	Low Priority
E-24	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-25	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	2	3	0	0	0	None	5	Low Priority
E-26	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	2	3	0	0	0	None	5	Low Priority
E-28	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
E-29	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	3	3	0	0	0	None	6	High Priority
E-31	Unnamed Trib to Diversion Channel crossing Washington St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-16	Unnamed Tribs to Stone Brook Crossing Barnes St	0	0	0	0	1	0	0	3	0	None	4	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Inflow? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photography	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
H-13	Unnamed Tributary To Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-21	Unnamed Tributary To Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-22	Unnamed Tributary To Dark Brook	0	0	0	0	1	3	0	0	1	None	5	Low Priority
H-23	Unnamed Tributary To Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-24	Unnamed Tributary To Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-25	Unnamed Tributary To Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-27	Unnamed Tributary To Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-28	Unnamed Tributary To Dark Brook	0	0	0	0	2	3	0	0	1	None	6	High Priority
H-29	Unnamed Tributary to Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-30	Unnamed Tributary to Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-31	Unnamed Tributary To Dark Brook	0	0	0	0	2	3	0	0	0	None	5	Low Priority
H-32	Unnamed Tributary To Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-33	Unnamed Tributary to Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-34	Unnamed Tributary to Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-59	Unnamed Tributary to Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-60	Unnamed Tributary to Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
H-63	Unnamed Tributary to Dark Brook	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-10	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-11	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-12	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-13	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	1	None	5	Low Priority
G-14	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-15	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-16	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-17	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
G-18	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	2	3	0	0	0	None	5	Low Priority
G-24	Unnamed tributary to Dark Brook Reservoir crossing Heritage Dr	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-19	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-20	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-24	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-25	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
C-26	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-27	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-28	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-29	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-30	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-31	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-32	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-33	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-37	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-72	Unnamed Tributary to Leesville Pond along Boyce St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-18	Unnamed Tributary to Leesville Pond Crossing Sumner St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-34	Unnamed Tributary to Leesville Pond Crossing Sumner St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-36	Unnamed Tributary to Leesville Pond Crossing Sumner St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-38	Unnamed Tributary to Leesville Pond Crossing Sumner St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-39	Unnamed Tributary to Leesville Pond Crossing Sumner St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
C-60	Unnamed Tributary to Leesville Pond Crossing Sumner St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-01	Unnamed tributary to Stone Brook along Potter Farm Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-02	Unnamed tributary to Stone Brook along Potter Farm Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-03	Unnamed tributary to Stone Brook along Potter Farm Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-04	Unnamed tributary to Stone Brook along Potter Farm Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
M-09	Unnamed tributary to Stone Brook along Potter Farm Rd	0	0	0	0	2	3	0	0	0	None	5	Low Priority
M-20	Unnamed tributary to Stone Brook along Potter Farm Rd	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-01	Unnamed Tributary to Stoneville Pond Crossing Burnett St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-29	Unnamed Tributary to Stoneville Pond Crossing Burnett St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-30	Unnamed Tributary to Stoneville Pond Crossing Burnett St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-05	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-06	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-07	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-08	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-09	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-10	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority

Outfall ID	Receiving Water	Previous Screening Results Indicate Likely Sewer Input? ¹	Discharging to Area of Concern to Public Health? ²	Frequency of Past Discharge Complaints	Receiving Water Quality ³	Density of Generating Sites ⁴	Age of Development/Infrastructure ⁵	Historic Combined Sewers or Septic? ⁶	Aging Septic? ⁷	Culverted Streams? ⁸	Additional Characteristics	Score	Priority Ranking
Information Source		Outfall inspections and sample results	GIS Maps	Town Staff	Impaired Waters List	Land Use/GIS Maps, Aerial Photograph	Land Use Information, Visual Observation	Town Staff, GIS Maps	Land Use, Town Staff	GIS and Storm System Maps	Other		
Scoring Criteria		Yes = 3 (Problem Outfall) No = 0	Yes = 3 No = 0	Frequent = 3 Occasional = 2 None = 0	Poor = 3 Fair = 2 Good = 0	High = 3 Medium = 2 Low = 1	High = 3 Medium = 2 Low = 1	Yes = 3 No = 0	Yes = 3 No = 0	Yes = 3 No = 0	TBD		
B-11	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
B-12	Unnamed Tributary to Stoneville Pond Crossing Rochdale St	0	0	0	0	1	3	0	0	0	None	4	Low Priority
K-01	Wellington Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
K-02	Wellington Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
K-03	Wellington Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority
K-04	Wellington Brook	0	0	0	0	1	0	0	3	0	None	4	Low Priority

Scoring Criteria:

¹ Previous screening results indicate likely sewer input if any of the following are true:

- Olfactory or visual evidence of sewage,
- Ammonia \geq 0.5 mg/L, surfactants \geq 0.25 mg/L, and bacteria levels greater than the water quality criteria applicable to the receiving water, or
- Ammonia \geq 0.5 mg/L, surfactants \geq 0.25 mg/L, and detectable levels of chlorine

² Outfalls/interconnections that discharge to or in the vicinity of any of the following areas: public beaches, recreational areas, drinking water supplies, or shellfish beds

³ Receiving water quality based on latest version of MassDEP Integrated List of Waters.

- Poor = Waters with approved TMDLs (Category 4a Waters) where illicit discharges have the potential to contain the pollutant identified as the cause of the impairment
- Fair = Water quality limited waterbodies that receive a discharge from the MS4 (Category 5 Waters)
- Good = No water quality impairments

⁴ Generating sites are institutional, municipal, commercial, or industrial sites with a potential to contribute to illicit discharges (e.g., car dealers, car washes, gas stations, garden centers, industrial manufacturing, etc.)

⁵ Age of development and infrastructure:

- High = Industrial areas greater than 40 years old and areas where the sanitary sewer system is more than 40 years old
- Medium = Developments 20-40 years old
- Low = Developments less than 20 years old

⁶ Areas once served by combined sewers and but have been separated, or areas once served by septic systems but have been converted to sanitary sewers.

⁷ Aging septic systems are septic systems 30 years or older in residential areas.

⁸ Any river or stream that is culverted for distance greater than a simple roadway crossing.