



**Table 4-1. SSO Inventory
Auburn, Massachusetts
Revision Date: September 26, 2019**

SSO Location ¹	Discharge Statement ²	Date ³	Time Start ³	Time End ³	Estimated Volume ⁴	Description ⁵	Mitigation Completed ⁶	Mitigation Planned ⁷
101 Southbridge St	Contained in catch basin	07/27/2016	09:00	23:00	<10,000 gals	Cracked pipe	Pipe replaced	
Upland Street @ city line	Entered an intermittent stream	10/30/2017	14:00	19:00	<150,000 gals	Collapsed pipe	Pipe replaced	
Southbridge Street Court	Entered a drainage ditch	06/05/2018 06/06/2018	21:00	17:00	<10,000 gals	Cracked pipe	Pipe Replaced	

¹ Location (approximate street crossing/address and receiving water, if any)

² A clear statement of whether the discharge entered a surface water directly or entered the MS4

³ Date(s) and time(s) of each known SSO occurrence (i.e., beginning and end of any known discharge)

⁴ Estimated volume(s) of the occurrence

⁵ Description of the occurrence indicating known or suspected cause(s)

⁶ Mitigation and corrective measures completed with dates implemented

⁷ Mitigation and corrective measures planned with implementation schedules